Print to PDF

New Features

Contents

- 1. New Features

1. New Features

1.1 New Firmware for LINUS6.4 and LINUS V-Series:

- ADDED: LINUS6.4 & LINUS V: Improved Firmware stability (Adds a watchdog that monitors DSPs and restarts them if necessary)
- FIXED: LINUS6.4 & LINUS V: Fixes rare crashes or lockups and a condition where the amp couldn't be woken from standby
- FIXED: SPACE Panel presets weren't available on LINUS V908
- CHANGED: Improved current Limiter for LINUS V1804

> **Warning**
>
> Due to minimum firmware requirements, LINUS V-Series amplifiers that have firmware v4.20 or higher installed, can not be downgraded below firmware v4.20

> ⚠ **Warning**
>
> Due to essential component updates on the LINUS14 / LINUS14D and LINUS12C amplifiers, no backwards compatibility for firmware versions older than V x.69 is possible.
>
> Affected amplifiers starting with this serial number:
>
> - LINUS14/D: 19030863
> - LINUS12C: 21090214

Please refer to the document “LINUS Control v2.9.7 Known Issues” for further information.

Product	Firmware Version
LINUS V1804	v4.80
LINUS V908	v4.80
LINUS6.4	v4.80
LINUS14 / LINUS14-D	V3.70
LINUS12C	V3.71
LINUS10	V2.70
LINUS10-C	V5.70
LINUS5-C	V5.70
LINUS CON	V1.70