



New Features
- LINUS Control v2.9.4 –





- 1. *New Features* 3
 - 1.1. LINUS6.4 App3
 - 1.2. Minor Updates..... Error! Bookmark not defined.
 - 1.3. LINUS6.4 Firmware v3.10.....3



1. New Features

1.1. LINUS6.4 Firmware v3.20

- Fix: LINUS6.4 firmware v3.10 would not initialize the Analog inputs correctly when restoring power, leading to no audio output and "Amp Off" & Limiters shown on screen.
- Fix: The WiFi hotspot in LINUS6.4 would sometimes stop working after a couple of days.

1.2. Subnet Mask Configuration

- It is now possible to configure the subnet mask for LINUS6.4 in LINUS Control on the Amps page.

1.3. Minor Changes

- Fix: LINUS6.4 Mute status in LINUS Control is now in sync with the Mute button of the amplifier.
- Fix: The PEQ type drop down in the Tuning view for PEQ 6&7 would sometimes be hidden by other UI elements.

IMPORTANT

Due to essential component update on the LINUS14 / LINUS14D and LINUS12C amplifiers, no backwards compatibility to firmware versions older than V x.69 is possible.

Affected amplifiers starting with this serial number:

LINUS14/ D: 19030863

LINUS12C: 21090214

Please refer to document "LINUS Control v2.9.3 Known Issues" for further information.

Product	Firmware Version
LINUS6.4	V3.20
LINUS 14 / LINUS14-D	V3.70
LINUS12C	V3.71
LINUS10	V2.70
LINUS10-C	V5.70
LINUS5-C	V5.70
LINUS CON	V1.70