

CODA

C O D A A U D I O



Known Issues
- LINUS Control v2.0.34 -





1. Known Issues

Key	Components	Description	Workaround
#1208	LINUS14 / CON / 10	2WAY Preset routing and tuning parameters are not linked together between channels on Front Panel when in standalone mode.	If using Amplifiers in standalone mode, IE no LINUS Control, if 2WAY preset is used, routing, gain, delay & other filters need to be applied individually to both channels of speaker.
#1213	LINUS Control	MacOS Firewall can sometimes prevent connections, even with LC nominated as an 'Allowed' App. It typically will allow LC to connect, but if LC is closed, then re-opened, connections may not be possible.	Disable MacOS Firewall.
#1214	LINUS Amplifiers	Front Panel LCD does not report the correct serial number.	Check the sticker on the rear of the amplifier to determine the amplifier serial number.
#1215	LINUS Control LINUS14 / CON / 10	After updating firmware on LINUS14 / CON / 10 in LINUS Control, they may reappear in the discovery list stating they need the Firmware Updating (again).	Power Cycle the amplifiers after the Firmware Update process is complete & this error will be cleared.
#1216	LINUS Amplifiers	Front Panel LCD reports "LINUS LIVE ONLINE" and "LINUS LIVE OFFLINE" rather than "LINUS CONTROL ONLINE" and "LINUS CONTROL OFFLINE".	
#1217	LINUS Control	If 2-byte language is selected for Operating System, the text of some messages may be clipped in the application window.	